




RRL measurements on July 7th and 10th

M. Sapinski,

thanks to: S. Lindner, T. Weber, L. Fernandez
PSI, July 16th, 2025





Goals

- Collect missing data points for scans with various bias voltages.
- Investigate efficiency of new RRL cleaning procedure.
- Collect and analyze dust samples.



EIC interlocks

1. RRL is in proximity of injection septum, which is electrostatic element with voltage of ~ 133 kV.
2. RRL scans provoke sudden jumps in dark current \rightarrow sparks in EIC \rightarrow interlocks.
3. Interlock probability depends on the beam intensity \rightarrow tests done at 1.7 mA.
4. Before cleaning: 3 interlocks/scan (over 11 scans).
5. After cleaning: 0.2 interlocks/scan (over 5 scans).



Dust collection


- The transmission belts are very difficult to clean because of a difficult access.
- We have run the scan while keeping the cleaning tissue in one location, this way accessing the whole length of the belt.
- In addition, a build up of metallic dust at the very end of RRL structure was seen and cleaned.



Gamma spectroscopy of the dust sample from belt (Marco and Dominik)

- It looks more like stainless steel (Mn-54, Mn-52, Co-57), NOT aluminum (lack of Na-22, Na-24).
- RRL transmission belt is made of stainless steel.

Spectrum



- It is possible to reduce EIC interlocks generated by RRL by careful cleaning and regular removal of the metallic dust.
- The dust composition suggests that it comes from stainless steel elements, most likely transmission belts.
- The cleaning procedure should be executed regularly, together with servicing the RRL wires.